





YS-264




Order	(L*W) MM
①	520*445=1
②	520*445=1
③	505*445=1
④	1170*78=1
⑤	1170*78=2
⑥	1170*60=2
⑦	599*230=1
⑧	599*230=1
⑨	209*84=2
⑩	209*84=2
⑪	558*283=2
⑫	599*230=1
⑬	599*230=1
⑭	558*84=2
⑮	558*283=2




A




V



C



F



∅15*13mm
=24

∅8*40mm
=24

∅8*40mm
=2


∅20*0.3mm=24

YG-A004


H-H

I

J




300*40*40mm
=4



67*67*40mm
=2



4*14mm
=150




∅20*8mm
=3

K




∅10*43mm
=3

L




∅6*70mm
=3

W



35*300*107mm
=4

X




25*25*31mm
=4

P




∅18*4mm
=6

U




170*240*87mm
=2

N




∅4*30mm
=4

1




2



C=2*




3



N=2*


4



V=4*




5




A=4*
⊕

6




N=2*
⊕

7




V=20*
⊕

8




A=10*
⊕

9




A=10* 

10




H-H=2* 
I=16* 

11




I=7* 

12



I=4* 


13



$I=10*$




14



$I=4*$




15



$I=2*$




16



$X=2*$
 $I=8*$




17



I=6*




18



I=4*




19



I=4*




20



I=2*




21



$X=2*$
 $I=8*$




22




$G-G=4*$
 $I=24*$




23




24




25




26




27



28




l=8* 




F=24


29




30



31




32



$L=3*$
 $J=3*$

$J=3*$

OK!



P=6

