



YS-GT4070				
Order (L*W) MM 1 2 3 4 5 6 7 8 9 700*130=1 700*130=1 123*370=1 123*370=1 370*60=1 370*60=1 102*369=1 102*369=1 380*680=1 400*700=1				
3mm - 3.2mm				

A V N-N F				
ø15*13mm =16 ø8*40mm =16 ø20*10mm =8 ø20*0.3mm =16				
K L G-B I J				
ø10*43mm =4 ø6*70mm =4 DTC-C80 =2 4*14mm =12 ø20*8mm =4				
AA AB AC AD				
ø7.5*16mm =2 80mm*60mm =1 ø2.6*12mm =3 ø10mm =1				


1




3




AD=1*




2




4




V=16*




5




6




A=8*




7




8




AB=1*



AA=2*




9




A=8*




11




10




12




AC=3*




13




G-B=2*
I=12*




14




15



F=16




16




17


$K=4*$




18





19










OK!



YS-GT4070

②







Order	(L*W) MM
①	700*130=1
②	700*130=1
③	123*370=1
④	123*370=1
⑤	370*60=1
⑥	370*60=1
⑦	102*369=1
⑧	102*369=1
⑨	380*680=1
	400*700=1

A

 $\angle$

N-N



Ø15*13mm
=16

Ø8*40mm
=16






$\phi 20 \times 10 \text{ mm}$
=8

Ø20*0.3mm=16



BB

11






Ø10*43mm
=4






Ø6*70mm
=4

DTC-C80
=2
$$4 \times 14 \text{ mm} = 12$$


Ø20*8mm
=4




3mm-3.2mm




1




3




2




4




V=16*




A=8*




5




A=8*



7





F=16







6


G-B=2*
I=12*




In same level




9






10



11




L




R


K=4*




12



14



13



OK!

