


Assembling instruction



Install base first. Must buckle tree first when install the last steel pipe. Put down the tree slowly to prevent damage.

Hang the light string to the top of the tree, then untie the rope at the bottom and arrange the lights in order. Be patient, SO as not to knot the light bar.



Put the star on the top of the tree and turn on the power.