







YS - 355



Order	(L*W) MM
①	520*445=1
②	520*445=1
③	960*78=1
④	960*78=2
⑤	960*60=1
⑥	960*60=1
⑦	990*257=1
⑧	400*84=1
⑨	400*84=1
⑩	940*283=1
⑪	990*257=1
⑫	940*84=1
⑬	940*283=1




A




Ø15*13mm
=20

V




Ø8*40mm
=20

P




Ø18*4mm
=4

F




Ø20*0.3mm=20

YG-A0004




300*40*40mm
=2

H-H




67*67*40mm
=2

I



4*14mm
=83

J




Ø20*8mm
=3

K




Ø10*43mm
=3

L




Ø6*70mm
=3

W




35*300*107mm
=2

X



25*25*31mm
=2

U




170*240*87mm
=1

Z




120*34mm
=2


1




2



3




4



$A=10^*$ 


$A=10^*$ 

5




H-H=2*
I=16*

7




I=4*
I=16*

6




I=7*
I=16*

8



I=10*
I=16*


9



$l=4*$




10



$l=2*$



11




$X=1*$



$l=4*$



12




$l=6*$




13

$l=4*$




14

$l=4*$




15

$l=2*$




16

$X=1*$
 $l=4*$




17




YG-A004
l=12*


18




19




20



21




22




I=4*



23



F=20




24





Z=2*


I=4*



25




26



K=3*



27




L=3*

J=3*





28



J=3*



OK!



P=4