






YS-TC822



Order	(L*W) MM
①	460*519=1
②	460*519=1
③	960*78=1
④	960*78=1
⑤	460*988=1
⑥	960*60=1
⑦	960*60=1
⑧	956*235=1
⑨	400*84=1
⑩	400*84=1
⑪	940*283.5=1
⑫	956*235=1
⑬	940*84=1
⑭	940*283.5=1




A




Ø15*13mm
=19

V




Ø8*40mm
=19

P




Ø18*4mm
=4

F




Ø20*0.3mm =35

YG-A004




300*40*40mm
=2

H-H




67*67*40mm
=2

I



4*14mm
=83

J




Ø20*8mm
=2

K




Ø10*43mm
=2

L




Ø6*70mm
=2

W




35*300*107mm
=2

X




25*25*31mm
=2

U



170*240*87mm
=1

AG




Ø7*35mm
=8

AH




Ø10*9.5mm
=16

1




2

V=16*




3



A=8*




4




A=8*




5




6




7



8




9



$l=7*$




10



$l=4*$




11



$l=10*$




12



$l=4*$




13



$l=2^*$



14




$X=1^*$



$l=4^*$




15



$l=6^*$




16



$l=4^*$




17




I=4*


18




I=2*


19




X=1*
I=4*
 

20




YG-A004*
I=12*



21




22




23




24




25



26




27




28

$K=2^*$




29

$L=2^*$
 $J=2^*$




30

$J=2^*$



31

$P=4$



OK!