








YS-TC802



Order	(L*W) MM
①	400*519=1
②	400*519=1
③	570*78=1
④	570*78=1
⑤	400*598=1
⑥	570*60=1
⑦	570*60=1
⑧	566*235=1
⑨	205*84=1
⑩	205*84=1
⑪	550*283.5=1
⑫	566*235=1
⑬	550*84=1
⑭	550*283.5=1




A




ø15*13mm
=19

V




ø8*40mm
=19

P




ø18*4mm
=4

F




ø20*0.3mm =35

YG-A0004




300*40*40mm
=2

H-H




67*67*40mm
=2

I



4*14mm
=83

J




ø20*8mm
=2

K




ø10*43mm
=2

L




ø6*70mm
=2

W




35*300*107mm
=2

X




25*25*31mm
=2

U



170*240*87mm
=1

AG




ø7*35mm
=8

AH




ø10*9.5mm
=16

1




2

V=16*



3




A=8*




4


A=8*




5




6




7



8




9



$l=7*$




10



$l=4*$




11



$l=10*$




12



$l=4*$




13



$l=2*$



14




$X=1*$



$l=4*$




15



$l=6*$




16



$l=4*$




17




I=4*


18




I=2*


19




X=1*
I=4*
 

20




YG-A004*
I=12*



21




22




23



24




25




$l=4*$




26




$F=35$



27



28




$K=2*$




29

$L=2^*$
 $J=2^*$




30

$J=2^*$



31

$P=4$



OK!