





YS-C2-80


A + B = AB




A V P F YG-A005 H-H I J




∅15*13mm
=20




∅8*40mm
=20




∅18*4mm
=4




∅20*0.3mm=20




305*45*45mm
=2




67*67*40mm
=2




4*14mm
=83




∅20*8mm
=2




∅10*43mm
=2




∅6*70mm
=2



35*300*107mm
=2




25*25*31mm
=2




170*240*87mm
=1


1




2




V=20*




3




4




A=10*




A=10*





5




H-H=2*
I=16*



7




I=4*



6




I=7*


8




I=10*



9




I=4*




11




X=1*




I=4*




10




I=2*



12





I=6*





13

I=4*





14

I=4*



15




I=2*




16

X=1*


I=4*




17




YG-A005





I=12*






19




18




20




21




23




22




I=4*




24




25




K=2*




27





J=2*




26




L=2*
J=2*



28



P=4



OK!