






Windsor

1299_141799



Vu-A1		2175mm	x4	1/1	Vu-23			x2	1/1
Vu-C5		1900mm	x2	1/1	GY-15			x2	1/1
Vu-C6		1900mm	x2	1/1	GY-16			x1	1/1
Vu-B7		1855mm	x1	1/1	Vu-21			x68	1/1
Vu-B7a		1855mm	x1	1/1	Vu-26			x76	1/1
Vu-B8		1100mm	x1	1/1	Vu-C30		M8x10	x24	1/1
Vu-B8a		1100mm	x1	1/1	Vu-C31		M8	x24	1/1
Vu-2a		400mm	x2	1/1	Vu-C32		ST5x35	x16	1/1
Vu-2b		800mm	x2	1/1	Vu-C33		ST5x10	x12	1/1
Vu-A10		1525mm	x1	1/1	Vu-C34		ST4.8x16	x114	1/1
Vu-B10		1374mm	x1	1/1	Vu-C35		M5x15	x8	1/1
Vu-11		800mm	x1	1/1	Vu-C36		M5	x8	1/1
Vu-A16a		1751.5mm	x2	1/1	Vu-C37		M6x25	x8	1/1
Vu-A16b		1751.5mm	x2	1/1	Vu-C38		M6x40	x6	1/1
Vu-B16a		996.5mm	x2	1/1	Vu-C39		M6	x14	1/1
Vu-B16b		996.5mm	x2	1/1	Vu-C40		M6	x14	1/1
Vu-C17		1806mm	x4	1/1	Vu-C41		M8x31	x68	1/1
Vu-C15		1841mm	x38	1/1	Vu-C42		M4x10	x80	1/1
Vu-8			x4	1/1	Vu-C43		M4x10	x16	1/1
Vu-10b			x1	1/1	Vu-C44		M4	x20	1/1
Vu-10c			x3	1/1	Vu-C45		M8x70	x16	1/1
Vu-10d			x1	1/1					
Vu-10e			x3	1/1					
Vu-13			x8	1/1					
Vu-14			x4	1/1					
Vu-18			x4	1/1					
Vu-20			x2	1/1					
Vu-22			x1	1/1					

FR : SAV/INFORMATION /VIDEO/CONTACT

EN: AFTER-SALES SERVICE/INFORMATION/VIDEO/CONTACT

DE : REPARATUR-SERVICE UND ERSATZTEILE /INFORMATIONEN /VIDEO/KONTAKT

ES: SERVICIO POST-VENTA/INFORMACIÓN/VIDEO/CONTACTO

IT: SERVIZIO ASSISTENZA/INFORMAZIONI/VIDEO/CONTATTO




PT: SERVIÇO PÓS-VENDA/INFORMAÇÕES/VIDEO/CONTATO

PL: SERWIS TECHNICZNY/INFORMACJE/WIDEO/KONTAKT


NE: AFTER SALES SERVICE/INFORMATIE/VIDEO/CONTACT

HE: עם לתקשר/הווידיאו/ מידע/ומכירות שירות לאחר



SAV.HABITATETJARDIN.COM




1	 Vu-A1 x4	 Vu-8 x4	 Vu-C32 x16	
---	---	--	---	--





2	 Vu-C5 x2	 Vu-C6 x2	 Vu-2b x2	 Vu-C34 x36	
---	--	--	--	--	--





3	 Vu-13 x4	 Vu-C30 x12	 Vu-C31 x12	
---	--	--	--	--





4	 Vu-B7 x1	 Vu-B8 x1	 Vu-2a x1	 Vu-C34 x12	
---	--	--	--	--	--





5							
	Vu-13 x2	GY-15 x1	Vu-C30 x6	Vu-C31 x6	Vu-C38 x3	Vu-C39 x3	Vu-C40 x3






6	 Vu-B7a x1	 Vu-B8a x1	 Vu-2a x1	 Vu-C34 x12	
---	---	---	--	--	--







7							
	Vu-13 x2	GY-15 x1	Vu-C30 x6	Vu-C31 x6	Vu-C38 x3	Vu-C39 x3	Vu-C40 x3















9	 Vu-20 x2	 GY-22 x1	 Vu-C34 x8	 Vu-C42 x4	 Vu-C44 x4	
---	--	--	---	---	---	--







10	 Vu-A16a x2	 Vu-10b x1	 Vu-10c x1	 Vu-C35 x2	 Vu-C36 x2	 Vu-C39 x2	
----	--	---	---	---	---	---	--




11	 Vu-A16b x2	 Vu-10d x1	 Vu-10e x1	 Vu-C35 x2	 Vu-C36 x2	 Vu-C39 x2	
----	--	---	---	---	---	---	--



12							
	Vu-B16a x2	Vu-B16b x2	Vu-10c x2	Vu-10e x2	Vu-C35 x4	Vu-C36 x4	Vu-C39 x4



13	 Vu-18 x2	 Vu-C43 x8	 Vu-C44 x8	
----	---	--	--	--



14





Vu-18 x2







Vu-C43 x8



Vu-C44 x8



15	Vu-21 x34	Vu-C41 x34	
--	--	---	--





16





Vu-21 x34





Vu-C41 x34















20



Vu-C45 x16



A=B








20







2024-2025

21











Vu-C34 x8











23	 Vu-C15 x38	 Vu-26 x76	
---------------	---	--	--











26







Vu-C42 x2








27







Vu-C42 x36



28	 Vu-C17 x4	 Vu-C37 x8	 Vu-C40 x8	
----	--	--	--	--



29	 Vu-14 x4	 Vu-C33 x12	 GY-16 x1	
----	---	---	---	--








30



Vu-23 x2



Vu-C34 x8



30

2024-2025

Responsable de la commercialisation du produit / Company in charge of commercializing the product / Responsable de la comercialización del producto / Responsabile della commercializzazione del prodotto:

GECODIS SA

32, rue de paradis

75010, Paris, France

Service commercial/ Commercial service/ Servicio comercial / Servizio commerciale :

Habitatetjardin.com

32, rue de paradis

75010, Paris, France

Assistance : +33 (0) 1 47 70 33 64

Service après-vente/ After sale services/ Servicio post-venta / Servizio dopo vendita:

GECODIS SA

32, rue de paradis

75010, Paris, France

<http://sav.habitatetjardin.com>