


GV320-22



Do not use excessive force when the connector is tightened

Installation Diagram