








YS-C4-120







Order	(L*W) MM
①	520*445=1
②	520*445=1
③	505*445=1
④	1170*78=1
⑤	1170*78=2
⑥	1170*60=2
⑦	209*84=2
⑧	209*84=2
⑨	558*283.5=2
⑩	558*84=2
⑪	558*283.5=2

A

V

C

F



∅15*13mm
=24

∅8*40mm
=24

∅8*40mm
=2





∅20*0.3mm=24

K

L

W

AN



∅10*43mm
=3

∅6*70mm
=3

35*300*107mm
=4





14*14*32mm
=4

YG-A005

H-H

I

J



305*45*45mm
=4

67*67*40mm
=2




4*14mm
=150

∅20*8mm
=3

P

U

N




∅18*4mm
=6


170*240*87mm
=2

∅4*30mm
=4


1




2




C=2*



3




4




N=2*


V=4*




5




A=4*




7




V=20*




6



N=2*




8




A=10*



9




10



A=10*





11



12



H-H=2*




I=16*

I=24*

I=6*





YG-A005





13

I=4*





14

I=4*





15

I=2*




16


AN=1*




17




18




19




20



I=6*






I=4*





21

I=4*





22

I=2*






23


AN=1*
I=4*




24




25




27




I=4*




26




I=7*



28





I=10*





29

I=4*





31

AN=1*
I=4*






30


I=2*




32




33




35



34




36




I=4*

I=10*

37




I=4*





I=2*


39




40





AN=1*
I=4*




41



43




42




I=8*


44




45




K=3*




47




J=3*




46




L=3*




J=3*



48



P=6



OK!